

24/09/2025

Geelong Waste Water Septic Servicing Report



Job Details		Job ID: GWW4771	
Client:	Pams Dog Day Club		
Site Contact:	[REDACTED]		
Technician:	[REDACTED]		
Site Address:	1-7 Nobility St, MOOLAP, VIC 3224		
System Type:	Domestic	Council/Shire:	COGG
System Name:	Icon Septech 3000 Domestic	Service Type:	Standard Service

Control Panel Operational?	Good	
Cleaned & Sprayed for Vermin?	Yes	
Alarm Status?	On	Circ pump switched of until tank fills
HI Water Indicator Status?	Off	
P1 Circulation Pump Operating?	Yes	
P2 Irrigation Pump Operating?	Yes	
P3 Air Pump Alarm Operating?	N/A	
P4 Sludge Return Pump Operating?	Off	No Sludge Return Pump
Is Septic Tank Accessible?	Yes	
Septic Tank Visual Effluent Quality:	Good	
Sludge in Septic Tank?	No	
Sludge in Circ Tank?	No	
Sludge in Irrigation Tank?	No	
Roots in tank?	None	
Irrigation Strainer/Filter Cleaned?	System has no filter	
Chlorination tablets Added?	N/A	
Irrigation Field?	Good	

Notes:	Installed saddle to septic tank	
Service Technician Name:	[REDACTED]	
Service Technician Signature:	[REDACTED]	

This copied document is made available for the sole purpose of enabling its consideration and review as part of a planning process under the Planning and Environment Act 1987. The document must not be used for any purpose which may breach copyright legislation